

A + B

IMPORTANT



IBM Options

IBMFabricMgrFlexCh1YSandS

Date: 2013-05-07

(1P)PN: 00D4692

(S) S/N: KQ8G0NA



(1S) P/N S/N: 00D4692KQ8G0NA

(4L) Origin: MX



Printed in MEXICO.

This product contains the following serialized commodities (list is not inclusive of all parts inside)

GTIN:




CE



Batteries

DO NOT DISCARD

Waste is here





IBM Feature Activation Instructions

FoD option: IBM Fabric Manager

Option P/N or Product ID: 00D4692

Feature code: A80E

Quantity ordered: 4

Plant order: K1XKWW

Sales order: 2077025869

Authorization code: DI2IBAAAAAAA7377356699

To activate your FoD option, complete the following steps:

1. Locate the authorization code at the top of this document.
2. Make sure that you have access to the hardware that you want to activate.
3. Login at <http://www.ibm.com/systems/x/fod/>.
4. Select **Request activation key** from the left navigation pane.
5. Enter the authorization code and click **Continue**.
6. Follow the instructions on the web page to activate the Features on Demand option and verify that the request is successful.

The activation key file is sent to the email address that you provide during the activation process.

For more detailed information, including instructions for automating the activation and installation of the activation key by using IBM ToolsCenter or IBM Director, see the *Features on Demand - User's Guide* at <http://www.ibm.com/systems/x/fod/> under Help section.

If you require additional assistance, contact your IBM marketing representative or authorized reseller.

For Manufacturing Use Only

Plant order: K1XKWW

(S) Part Number: 00D4692 + (Q) Qty: 4 + K1XKWW



MFGN: 0K1XKWW

Work Order: PBCBCBP001

Printed in MEXICO

Sales order: 2077025869

(1P) Part Number: 00D4692



Qty: 4